

AREA # 12 INSPECTION COUNT 1

CITY OF SAN JOSE BUILDING DIVISION 801 North First Street, Room 200, San Jose, CA 95110
REROOF PROGRESS/FINAL INSPECTION AND COMPLETION VERIFICATION

PERMIT # B9667666 DATE SCHEDULED M T W TH F 6-7 /1996

JOB ADDRESS(ES) 916 Meridian Ave CALL NEEDED YES X NO
PHONE # 415 937-1299

STORE NAME/LOCATION DATE REC. 6-5 BY
REQUESTED BY: Delfino CONTR/OWNER Water Prody + ASXC

() SFR/DUP 1 STORY 2 STORY X COM/IND/MULTI-FAM/OTHER
LIST OF OBSERVATIONS TO BE COMPLETED PRIOR TO VERIFYING COMPLETION: **EXPIRED**

IN - PROG. DICK SO FAR
1) COUNTER FLASH TOP EDGE CAP SHI.

(NOTE THAT (EX) ROOF HAS ONLY ONE (EX) DRAIN & NO OVERFLOW.)

1. () Progress/Final Inspection NOT approved. Complete the listed items above and recall for inspection.
2. X Progress Inspection is completed. Progress inspection observed proper installation except items noted above. Mail in this completion verification once all noted corrections are made and installation is completed.
3. () Final Inspection Approved.

DATE 6/7/96 INSPECTOR: PRINT SUE JAMIESON SIGN Sue Jamieson

COMPLETION VERIFICATION
If Box 2 above is checked, then the following must be completed by the licensed contractor or building owner and mailed to the City of San Jose Building Division, 801 North First Street, Room 200, San Jose, CA 95110 to finalize the permit. This form when properly completed constitutes the final inspection.

I verify that all of the listed items above were completed and that the completed roof was installed in accordance with the California State Building Code and all applicable manufacturer's requirements:

LICENSED CONTRACTOR: PRINT SIGN LIC. NO. DATE
OR BUILDING OWNER
(Rev 3/20/96) WHITE - OFFICE CANARY - INSPECTOR PINK - COMPLETION RETURN FORM HARD COPY - OWNER